

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Priscilla Burton Environmental Scientist III				
Company	Vicky S. Miller Environmental Specialist				

Inspection Report

Permit Number:	C0070039		
Inspection Type:	TECHNICAL		
Inspection Date:	Monday, November 24, 2008		
Start Date/Time:	11/24/2008 1:00:00 PM		
End Date/Time:	11/24/2008 4:30:00 PM		
Last Inspection:	Thursday, October 23, 2008		

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sun 50 F

InspectionID Report Number: 1848

Accepted by: jhelfric

Monday, December 01, 2008

Date

12/8/2008

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

9,471.00	Total Permitted		
51.10	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ✓ State □ Surface Loadout County Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Observed ongoing topsoil salvage from G 22 access road and pad. Observed partially constructed topsoil stockpile on pad of G17. Photos from this site visit are located in the 11242008 images folder.

Inspector's Signature

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070039 Inspection Type: TECHNICAL

Inspection Date: Monday, November 24, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers				
3.	Topsoil	✓		~	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance		· []		
22.	Other				

Permit Number: C0070039
Inspection Type: TECHNICAL

Inspection Date: Monday, November 24, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The G-22 pad and access road construction was approved on November 10, 2008. Two rock trucks, two dozers and a hoe were operating to salvage and stockpile topsoil from G-22 onto the location of the abandoned G-17 site.

3. Topsoil

Topsoil pile under construction was kidney bean shaped: approximately 30 ft long X 20 ft. wide X 12 ft high. Topsoil stockpile surrounds several quaken aspen trees. Photo attached. Additional topsoil will be stockpiled on an adjacent sagebrush flat, to the west on the existing road from G17.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fence was installed below constructed road. Photo attached

18. Support Facilities, Utility Installations

G-22 pad was under construction with cut slope approximately 7 ft. high. One-quarter to one-third of the site had been stripped of topsoil and leveled. Photo attached.

Inspection Report #1848 Attachment 11/24/2008







